file:///U|/MSDS/Facilities/HVAC/Hardness%20Indicator.htm

TAYLOR CHEMICALS INC. -- R-0620 HARDNESS INDICATOR POWDER -- 6810-01-072-1979

Product ID:R-0620 HARDNESS INDICATOR POWDER MSDS Date:02/01/1992 FSC:6810 NIIN:01-072-1979 MSDS Number: BGKLX === Responsible Party === Company Name: TAYLOR CHEMICALS INC. Address:31 LOVETON AVE City:SPARKS State:MD ZIP:21152-9201 Info Phone Num: 301-472-4340 Emergency Phone Num: 301-472-4340 Preparer's Name: JOHN MCCAULEY CAGE: 89975 === Contractor Identification === Company Name: TAYLOR TECHNOLOGIES, INC Address: 31 LOVETON CIRCLE Box:City:SPARKS State:MD ZIP:21152 Phone: 401-472-4340 CAGE: 89975 ================ Ingred Name: NON-HAZARDOUS INGREDIENTS (INERT) Other REC Limits: NONE RECOMMENDED Ingred Name: SUCROSE CAS:57-50-1 RTECS #:WN6500000 OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3; 9192 _____ Routes of Entry: Inhalation:YES Skin:YES Ingestion: YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

file:///U|/MSDS/Facilities/HVAC/Hardness%20Indicator.htm

Health Hazards Acute and Chronic:EYES- IRRITANT. SKIN- IRRITANT. CONTACT MAY CAUSE STAINING. INGESTION- IRRITANT. INHALATION-IRRITANT.

Effects of Overexposure:TARGET ORGAN(S): EYES, SKIN, RESPIRATORY TRACT.

Medical Cond Aggravated by Exposure:EYE, SKIN, AND RESPIRATORY CONDITIONS.

First Aid:EYE AND SKIN CONTACT- IMMEDIATELY FLUSH EYES WITH WATER FOR 15 MINUTES. CALL PHYSICIAN. WASH SKIN THOROUGHLY WITH SOAP AND WATER. INGESTION- GIVE LARGE AMOUNTS OF WATER. CALL PHYSICIAN. INDUCE VOMITI NG UNDER DIRECTION OF PHYSICIAN. INHALATION- REMOVE TO FRESH AIR. CALL PHYSICIAN.

Flash Point:NONE

Extinguishing Media:DRY CHEMICAL, CARBON DIOXIDE, WATER SPRAY OR FOAM. Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING (POSITIVE PRESSURE IF AVAILABLE) APPARATUS AND FULL PROTECTIVE CLOTHING. Unusual Fire/Explosion Hazard:MAY EMIT TOXIC FUMES UNDER FIRE

CONDITION.

Spill Release Procedures:SWEEP UP. AVOID RAISING DUST. CONTAINERIZE FOR

LATER DISPOSAL.

Handling and Storage Precautions: AVOID CONTACT WITH EYES, SKIN, AND CLOTHING. AVOID BREATHING CHEMICALS.

Other Precautions:NONE

Respiratory Protection:DUST MASK. Ventilation:NONE SPECIFIED BY MANUFACTURER. Protective Gloves:GENERAL PURPOSE GLOVES. Eye Protection:SAFETY GLASSES. file:///U//MSDS/Facilities/HVAC/Hardness%20Indicator.htm

Other Protective Equipment:LAB COAT. Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING. Supplemental Safety and Health NONE

HCC:N1 Boiling Pt:B.P. Text:DECOMPOSES Spec Gravity:1.6 Solubility in Water:SOLUBLE Appearance and Odor:PURPLE POWDER,NO ODOR. Percent Volatiles by Volume:1

Stability Indicator/Materials to Avoid:YES
NONE SPECIFIED BY MANUFACTURER.
Stability Condition to Avoid:EXTREME HEAT, TEMPERTURES.
Hazardous Decomposition Products:CARBON MONOXIDE, NITROGEN OXIDES AND
PRODUCE OXYGEN.

Waste Disposal Methods: INCINERATION OR OTHER METHOD TO COMPLY WITH ALL LOCAL, STATE, AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their

particular situation.