

# **Material Safety Data Sheet**

Document Code: Wax/MW

Date of Preparation

Version: 03

March 12, 2003

# Section 1 - Product and Company Identification

PRODUCT NAME & NUMBERS

MINWAX® Paste Finishing Wax Rockler SKUs: 57547, 57554

8500 Natural

8600 Special Dark

HMIS CODES

Health 2
Flammability 2
Reactivity 0

MANUFACTURER'S NAME EMERGENCY TELEPHONE NO.

MINWAX Company (216) 566-2917

10 Mountainview Road INFORMATION TELEPHONE NO.

Upper Saddle River, NJ 07458 (800) 523-9299

## Section 2 – Composition/Information on Ingredients

|        |  |  |  | -  |
|--------|--|--|--|--|
| Minera | l Spir                                   | its  |  |  |
| ACGIH  | TLV                                      | 100  | ppm  | 2 mm   |
| OSHA   | PEL                                      | 100  | ppm  |  |
| C.I. S | C.I. Solvent Red 7                       |  |  |  |
| ACGIH  | TLV                                      | 0.5  | mg/m3  |  |
| OSHA   | PEL                                      | 0.5  | mg/m3  |  |
| Chromi | <br>m TTT                                | (ac (  | 'r)  |  |
| -      | ACGIH<br>OSHA<br>C.I. S<br>ACGIH<br>OSHA | ACGIH TLV OSHA PEL C.I. Solvent ACGIH TLV OSHA PEL | ACGIH TLV 100 OSHA PEL 100 C.I. Solvent Red 7 ACGIH TLV 0.5 OSHA PEL 0.5 | ACGIH TLV 100 ppm OSHA PEL 100 ppm C.I. Solvent Red 7 ACGIH TLV 0.5 mg/m3 OSHA PEL 0.5 mg/m3 |

#### Section 3 – Hazards Identification

ROUTES OF EXPOSURE

Exposure may be by INHALATION and/or SKIN or EYE contact, depending on conditions of use. To minimize exposure, follow recommendations for proper use, ventilation, and personal protective equipment.

EFFECTS OF OVEREXPOSURE

Irritation of eyes, skin and upper respiratory system. May cause nervous system depression. Extreme overexposure may result in unconsciousness and possibly death.

SIGNS AND SYMPTOMS OF OVEREXPOSURE

Headache, dizziness, nausea, and loss of coordination are indications of excessive exposure to vapors or spray mists. Redness and itching or burning sensation may indicate eye or excessive skin exposure.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE

None generally recognized.

CANCER INFORMATION

For Complete Discussion of Toxicology Data Refer to Section 11.

#### Section 4 – First Aid Measures

If INHALED: If affected, remove from exposure. Restore breathing. Keep warm and quiet.

If on SKIN: Wash affected area thoroughly with soap and water. Remove contaminated clothing and launder before re-use.

If in EYES: Flush eyes with large amounts of water for 15 minutes. Get medical attention.

If SWALLOWED: Do not induce vomiting. Get medical attention immediately.

Page 2 of 4 Wax/MW

# Section 5 – Fire Fighting Measures

FLASH POINT LEL UEL 100 °F PMCC 1.0 6.0

FLAMMABILITY CLASSIFICATION

Combustible, Flash above 99 and below 200  $^{\circ}\text{F}$  EXTINGUISHING MEDIA

Carbon Dioxide, Dry Chemical, Foam UNUSUAL FIRE AND EXPLOSION HAZARDS

Closed containers may explode when exposed to extreme heat. Application to hot surfaces requires special precautions. During emergency conditions overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.

SPECIAL FIRE FIGHTING PROCEDURES

Full protective equipment including self-contained breathing apparatus should be used. Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

#### Section 6 – Accidental Release Measures

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Remove all sources of ignition. Ventilate the area. Remove with inert absorbent.

## Section 7 – Handling and Storage

STORAGE CATEGORY - DOL Storage Class II
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Contents are COMBUSTIBLE. Keep away from heat and open flame. Consult NFPA Code. Use approved Bonding and Grounding procedures. Keep container closed when not in use. Transfer only to approved containers with complete and appropriate labeling. Do not take internally. Keep out of the reach of children.

## Section 8 – Exposure Controls/Personal Protection

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation. Avoid contact with skin and eyes. Avoid breathing vapor and spray mist. Wash hands after using.

These coatings may contain materials classified as nuisance particulates (listed "as Dust" in Section 2) which may be present at hazardous levels only during sanding or abrading of the dried film. If no specific dusts are listed in Section 2, the applicable limits for nuisance dusts are ACGIH TLV 10 mg./m3 (total dust), 3 mg./m3 (respirable fraction), OSHA PEL 15 mg./m3 (total dust), 5 mg./m3 (respirable fraction).

Removal of old paint by sanding, scraping or other means may generate dust or fumes that contain lead. Exposure to lead dust or fumes may cause brain damage or other adverse health effects, especially in children or pregnant women. Controlling exposure to lead or other hazardous substances requires the use of proper protective equipment, such as a properly fitted respirator (NIOSH approved) and proper containment and cleanup. For more information, call the National Lead Information Center at 1-800-424-LEAD(in US) or contact your local health authority.

VENTILATION

Local exhaust preferable. General exhaust acceptable if the exposure to materials in Section 2 is maintained below applicable exposure limits. Refer to OSHA Standards 1910.94, 1910.107, 1910.108.

Page 3 of 4 Wax/MW

## Section 8 – Exposure Controls/Personal Protection (continued)

RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear a properly fitted organic vapor/particulate respirator approved by NIOSH/MSHA for protection against materials in Section 2.

When sanding, wirebrushing, abrading, burning or welding the dried film, wear a particulate respirator approved by NIOSH/MSHA for protection against non-volatile materials in Section 2.

PROTECTIVE GLOVES

Wear gloves which are recommended by glove supplier for protection against materials in Section 2.

EYE PROTECTION

Wear safety spectacles with unperforated sideshields. OTHER PRECAUTIONS  $\label{eq:control_precaution} % \[ \begin{array}{c} (x,y) \\ (x,$ 

Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal.

## Section 9 – Physical and Chemical Properties

| PRODUCT WEIGHT                               | 6.71 lb/gal | EVAPORATION RATE    | Slower than Ether |  |  |
|--|-------------|---------------------|-------------------|--|--|
| SPECIFIC GRAVITY                             | 0.81        | VAPOR DENSITY       | Heavier than Air  |  |  |
| BOILING POINT                                | 300-395 °F  | MELTING POINT       | Not Available     |  |  |
| VOLATILE VOLUME                              | 73 %        | SOLUBILITY IN WATER | Not Available     |  |  |
| VOLATILE ORGANIC COMPOUNDS (VOC Theoretical) |             |                     |                   |  |  |
| 4.7 lb/gal Less Federally Exempt Solvents    |             |                     |                   |  |  |
| 4.7 lb/gal                                   | Emitted VOC |                     |                   |  |  |

# Section 10 – Stability and Reactivity

```
STABILITY - Stable

CONDITIONS TO AVOID - None known.

INCOMPATIBILITY - None known.

HAZARDOUS DECOMPOSITION PRODUCTS - By fire: Carbon Dioxide, Carbon Monoxide,

Oxides of Metals in Section 2

HAZARDOUS POLYMERIZATION - Will not occur
```

#### Section 11 – Toxicological Information

CHRONIC HEALTH HAZARDS

No ingredient in these products is an IARC, NTP or OSHA listed carcinogen.

Prolonged overexposure to solvent ingredients in Section 2 may cause adverse effects to the liver and urinary systems.

Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage.

## TOXICOLOGY DATA

| CAS No.     | Ingredient Name    |                 |  |  |
|-------------|--------------------|-----------------|--|--|
| 64742-88-7  | Mineral Spirits    | Mineral Spirits |  |  |
|             | LC50 RAT 4HR       | Not Available   |  |  |
|             | LD50 RAT           | Not Available   |  |  |
| Proprietary | C.I. Solvent Red 7 |                 |  |  |
|             | LC50 RAT 4HR       | Not Available   |  |  |
|             | LD50 RAT           | Not Available   |  |  |

Page 4 of 4 Wax/MW

## Section 12 – Ecological Information

ECOTOXICOLOGICAL INFORMATION - No data available.

# **Section 13 – Disposal Considerations**

WASTE DISPOSAL METHOD

Waste from these product may be hazardous as defined under the Resource Conservation and Recovery Act (RCRA) 40 CFR 261. Waste must be tested for ignitability and extractability to determine the applicable EPA hazardous waste numbers

Incinerate in approved facility. Do not incinerate closed container. Dispose of in accordance with Federal, State/Provincial, and Local regulations regarding pollution.

Section 14 - Transport Information - No data available.

## Section 15 – Regulatory Information

SARA 313 (40 CFR 372.65C) SUPPLIER NOTIFICATION

CAS No. CHEMICAL/COMPOUND Chromium Compound

% by WT % Element 1 0.1

TSCA CERTIFICATION

All chemicals in these products are listed, or are exempt from listing, on the  $\operatorname{TSCA}$  Inventory.

#### Section 16 – Other Information

CANADIAN DISTRIBUTOR: Consumer Brands Canada Inc.

200 Confederation Parkway

Vaughn, ON L4K 4T8

NOTE: These products have been classified in accordance with the hazard criteria of the CPR and the MSDS contains all of the information required by the CPR.

The above information pertains to these products as currently formulated, and is based on the information available at this time. Addition of reducers or other additives to these products may substantially alter the composition and hazards of the product. Since conditions of use are outside our control, we make no warranties, express or implied, and assume no liability in connection with any use of this information.