## CIBA GEIGY CORP PLASTICS & ADDITIVES -- RP 70S -- 8030-00F040575

Product ID:RP 70S MSDS Date:08/04/1986 FSC:8030 NIIN:00F040575 MSDS Number: BXLYC === Responsible Party === Company Name: CIBA GEIGY CORP PLASTICS & ADDITIVES Address: THREE SKYLINE DRIVE City: HAWTHORNE State:NY ZIP:10532-2119 Country:US Info Phone Num:800-888-8372/914-347-4700 Emergency Phone Num: 800-888-8372/914-347-4700 Preparer's Name: PETER HENIGE CAGE:E0945 === Contractor Identification === Company Name: CIBA GEIGY CORP PLASTICS & ADDITIVES Address: THREE SKYLINE DRIVE City: HAWTHORNE State:NY ZIP:10532-2119 Country:US Phone:800-888-8372/914-347-4700 CAGE: E0945 Company Name: CIBA-GEIGY CORP ADDITIVES DIV. Address:SEVEN SKYLINE DRIVE Box:City:HAWTHORNE State:NY ZIP:10532-2119 Country:US Phone: 800-888-8372 CAGE:07566 Ingred Name: NON-HAZARDOUS INGREDIENTS Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Explanation of Carcinogenicity:NONE Medical Cond Aggravated by Exposure:SKIN & EYE CONDITIONS. First Aid: EYES: FLUSH W/WATER FOR 15 MINS. SKIN: (HANDCLEANER). INGESTION: IF CONSCIOUS, GIVE PLENTY OF WATER TO DRINK. DON'T INDUCE VOMITING. INHALATION: REMOVE TO FRESH AIR. GIVE OXYGEN/CPR IF NEEDED. OBTAIN MEDICAL ATTENTION IN ALL CASES. 

Flash Point:NONE

Extinguishing Media:CO2, FOAM, DRY CHEMICAL, WATER SPRAY Fire Fighting Procedures: USE SELF CONTAINED BREATHING APPARATUS. Unusual Fire/Explosion Hazard:NONE Spill Release Procedures: REMOVE BY ABSORBING IN ABSORBENT MATERIAL. Handling and Storage Precautions: HANDLE W/DUE CARE. Other Precautions: AVOID CONTACT W/EYES, SKIN & CLOTHING. ====== Exposure Controls/Personal Protection ========== Ventilation: MECHANICAL (GENERAL) & LOCAL EXHAUST IAW/ACGIH RECOMMENDATIONS. Eye Protection: SAFETY GLASSES Work Hygienic Practices: WASH THOROUGHLY AFTER HANDLING. Supplemental Safety and Health Boiling Pt:B.P. Text:190-220F Vapor Pres:20 Vapor Density:4.9 Spec Gravity:0.91 Solubility in Water:DISPERSIBLE Appearance and Odor: WHITE CREAMY EMULSION, W/NEUTRAL ODOR Percent Volatiles by Volume:80 Stability Indicator/Materials to Avoid:YES STRONG OXIDANTS; LIQUID CHLORINE & OXYGEN NITRIC ACID Waste Disposal Methods:DISPOSE OF IN ACCORDANCE W/LOCAL, STATE & FEDERAL REGULATIONS. Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.